Top 10 Tips

make sure your contractor measures up

- 1. Hire only licensed contractors.
- 2. Verify license status online at www.dpor.virginia.gov/LicenseLookup or call (804) 367-8511.
- 3. Check references + past work.
- 4. Get at least three estimates.
- 5. Insist on a written contract and don't sign anything until you completely understand the terms.
- 6. <u>Limit your deposit</u> to 10% down or \$1,000, whichever is less. (Up to 30% of total contract value in case of custom-made items.)
- 7. Don't let your payments get ahead of the work.
- 8. Don't pay 100% of the bill until the work is 100% complete.
- 9. Never pay cash.
- Keep a file of all payments and papers relating to your project (change orders, warranties, etc.).

